

## MINUTES OF THE BRENT CONNECTS - KINGSBURY AND KENTON Thursday 16 October 2025 at 6.00 pm

## 1. Action Log

Status key
Not completed
Progressing
Completed

Connect area:	Action	Statu s	Action description	Assigne Team				
	Residents raised concerns about the footpath leading into Roe Green Park from Kingsbury Road remains wet and difficult to walk on. Pedestrians are diverting onto the grass to pass through, which may cause further ground damage and accessibility concerns.		The Brent Parks Team will provide further details following confirmation of costs, the required surface materials, and the schedule for upcoming works.	Brent Team				
Kingsbur y & Kenton	A query was raised regarding the future of the lodge located in Roe Green Park. The question concerns what is planned for the building.		Brent Parks Team to follow up with Property and Licensing teams to obtain the status and any planned actions for the lodge. Feedback will be provided through this action log once information is available.	Brent Team/P es and Team				
	Residents had concerns about Brampton Road pavements which are in severe disrepair, causing frequent falls, especially among elderly and disabled residents.  Previous petitions and engagement with the council and MPs have not resulted in improvements.  Safety concerns include injuries and fatalities linked to pavement condition. Also, Brampton Road is a one-way street, but vehicles and motorbikes frequently travel in the wrong direction at high speed which increase the risk for school children and elderly		Highways and Enforcement teams to assess feasibility of installing cameras and implementing traffic control measures and to review pavement condition.	Highway Parking				

edestrians. Residents getting erbal abuse when residents		
hallenge drivers.		
Barriers at Kingsbury Roundabout have been broken or an extended period. The boundabout is very busy, and he lack of barriers poses a ignificant safety risks - highpeed vehicles potentially ausing accidents, risk of ehicles crashing into nearby ats and even though it has been reported multiple times and photographic evidence ubmitted to Highways, no hanges have been made.	Highways team to inspect the site and confirm to confirm next step and share updates.	Highwa Parking
Road markings and directional arrows on speed humps along salmon Street have completely aded, making them difficult to ee, especially at night. This coses a significant safety risk and could lead to accidents.	Highways team to inspect Salmon Street and confirm an update through the action log once works are planned.	Highwa Parking
Residents raised request about ne need for basic facilities such a toilets and a place for efreshments. Woodcock Park turrently lacks these amenities, miting its potential for community health initiatives.	Parks and Property teams provide update on explore funding and feasibility for installing toilets and refreshment facilities in Woodcock Park	Highwa Parking Team/B Parks T