

notes

 The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before proceeding with the works.

 Where an item is covered by drawings to different scales the larger scale drawing is to be worked to.

- Do not scale drawing. Figured dimensions to be worked to in all cases.

CDM Regulations 2007

ALL current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environmental Assessment

CDM Regulations 2007

ALL current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environmental Assessment Record.

date rev revision/author/checker

purpose of issue

for information

South Kilburn
Urban Regeneration

rawing

Proposed Masterplan Phasing Option D - All Phases

drawing no AA0461/1.1/051

drawn pxp checked bsc

scale @ A1 1:2500 date

PRP Architects © 10 Lindsey Street London EC1A 9HP T +44 (0)20 7653 1200

F +44 (0)20 7653 1201

lon.prp@prparchitects.co.uk



Jan '10