

## APPENDIX 2

### REPAIRS AND MAINTENANCE CONTRACTS

#### TENDER EVALUATION GRID

Area 1 Responsive Lot 1				
No.	Quality SCORE	Cost Score	Total Score	Ranking
1	33.07692308	29.83967	62.91659	4
2	-	-	-	-
3	-	-	-	-
4	23.84615385	18.22320	42.06935	6
5	-	-	-	-
6	34.61538462	41.19024	75.80562	2
7	38.46153846	34.98710	73.44864	3
8	-	-	-	-
9	31.53846154	28.65642	60.19488	5
10	-	-	-	-
11	43.07692308	36.81557	79.89250	1

Area 1 Planned Lot 2				
No.	Quality SCORE	Cost Score	Total Score	Ranking
1	-	-	-	-
2	-	-	-	-
3	33.07692308	41.308271	74.385194	5
4	24.61538462	28.192262	52.807646	9
5	40.76923077	33.042485	73.811716	4
6	36.92307692	32.065960	68.989037	7
7	36.92307692	38.067562	74.990639	3
8	34.61538462	43.798239	78.413623	2
9	33.07692308	34.165873	67.242796	8
10	33.84615385	36.247430	70.093583	6
11	43.07692308	40.564592	83.641516	1

Area 1 Voids Lot 3				
No.	Quality SCORE	Cost Score	Total Score	Ranking
1	36.15384615	18.14	54.29208553	0
2	-	-	-	-
3	33.07692308	37.90	70.97286911	2
4	23.07692308	5.51	28.59134834	8
5	39.23076923	20.28	59.51127272	4
6	36.92307692	16.17	53.0952251	6
7	39.23076923	22.56	61.79281737	3
8	32.30769231	34.10	66.40495902	2
9	33.84615385	23.45	57.29417729	5
10	30.76923077	20.66	51.42998427	7
11	40.00000	34.10	74.09727	1

Area 2 Responsive Lot 4				
No.	Quality SCORE	Cost Score	Total Score	Ranking
1	33.07692308	30.24	63.31292535	5
2	-	-	-	-
3	-	-	-	-
4	-	-	-	-
5	-	-	-	-
6	34.61538462	41.19	75.80615114	2
7	38.46153846	36.37	74.82661718	3
8	-	-	-	-
9	31.53846154	32.64	64.17486366	4
10	-	-	-	-
11	43.07692308	36.61	79.68353689	1

Area 2 Planned Lot 5				
No.	Quality SCORE	Cost Score	Total Score	Ranking
1	-	-	-	-
2	-	-	-	-
3	<b>33.07692308</b>	<b>41.35</b>	<b>74.42966398</b>	<b>4</b>
4	-	-	-	-
5	<b>40.76923077</b>	<b>32.95</b>	<b>73.72316994</b>	<b>5</b>
6	<b>36.92307692</b>	<b>31.93</b>	<b>68.85732946</b>	<b>7</b>
7	<b>36.92307692</b>	<b>37.90</b>	<b>74.82749322</b>	<b>3</b>
8	<b>34.61538462</b>	<b>43.63</b>	<b>78.24388704</b>	<b>2</b>
9	<b>33.07692308</b>	<b>34.04</b>	<b>67.11240741</b>	<b>8</b>
10	<b>33.84615385</b>	<b>36.12</b>	<b>69.96558306</b>	<b>6</b>
11	<b>43.07692308</b>	<b>40.49</b>	<b>83.56559827</b>	<b>1</b>

Area 2 Voids Lot 6				
No.	Quality SCORE	Cost Score	Total Score	Ranking
1	<b>36.92307692</b>	<b>18.07</b>	<b>54.99067811</b>	<b>8</b>
2	<b>38.46153846</b>	<b>18.06</b>	<b>56.52370439</b>	<b>7</b>
3	<b>33.07692308</b>	<b>37.77</b>	<b>70.84629787</b>	<b>1</b>
4	-	-	-	-
5	<b>39.23076923</b>	<b>19.96</b>	<b>59.19496471</b>	<b>5</b>
6	<b>36.92307692</b>	<b>16.04</b>	<b>52.96566232</b>	<b>9</b>
7	<b>39.23076923</b>	<b>22.54</b>	<b>61.77331317</b>	<b>4</b>
8	<b>32.30769231</b>	<b>33.61</b>	<b>65.91360416</b>	<b>2</b>
9	<b>33.84615385</b>	<b>23.93</b>	<b>57.77535428</b>	<b>6</b>
10	<b>30.76923077</b>	<b>20.29</b>	<b>51.05628394</b>	<b>10</b>
11	<b>40</b>	<b>21.79</b>	<b>61.78985487</b>	<b>3</b>