

Appendix 3: One Tree Hill and Mount Pleasant Existing Playground

One Tree Hill



Outdated playground equipment



Walking path is not DDA compliant (1.5m wide is the standard required)



Mount Pleasant



Rubbish and overflowing bins make Mount Pleasant uninviting



Outdated playground equipment



Poor Signage